

Technical Service Bulletin

Hammerhead Bladder Evaluation

ISSUE DATE:	May 24, 2013	TSB NUMBER	TSB-13-001
IOOOL DATE.	Way 24, 2013	TOD NOMBER	100-10-001

HAZARD / URGENCY RATING		
X	DANGER – Injury possible if TSB not observed or followed	
	WARNING – Product damage possible if TSB not observed or followed	
	CAUTION – Essential issue affecting operation, service, or parts	
	INFORMATIONAL – Advisory which may be of interest	

APPLICATION:

This Technical Service Bulletin applies to Hammerhead life preservers with the following serial numbers:

6760-05-070; 6760-05-085; 6760-05-124; 6760-05-141 6760-06-039; 6760-06-077; 6760-06-146; 6760-06-486 6760-07-0172; 6760-07-0173 6760-08-0021 6760-09-0044 6760-13-0001 through 6760-13-0031 inclusive

SUMMARY:

This Technical Service Bulletin requires that the above listed serial number Hammerheads be returned to Tulmar for evaluation of the air holding bladder to investigate a potential manufacturing defect.

IMPACT:

The potential manufacturing defect is related to the cut shape of the bladder and if left unchecked, could lead to premature rupture or tearing of one or both chambers in the bladder, thereby causing the bladder to rapidly leak air or fail to inflate.

ACTION:

Return Hammerheads with the above listed serial numbers to Tulmar for evaluation. Tulmar will replace the bladder if it is found to be defective. The Hammerhead will then be returned to the customer.

CONTACT:

For Return Material Authorization please contact the Tulmar Customer Service Department at (613) 632-1282 ext 240 or via email at amanda@tulmar.com.